

Version: V0.0.0
Author(s): BQ
Revised by: Jon Goitia
Effect date: 18/05/2018
Project: Hephestos 2

May 18th 2018



Changelog

| Version | Date | Changes | Author |
|---------|---------------------------|------------------|--------|
| V0.0.0 | May 18 th 2018 | Document created | BQ |
| | | | |
| | | | |
| | | | |



Contents

| Introduction | 4 |
|-------------------------|---|
| Updating firmware | 4 |
| First layer settings | 4 |
| Test Gcode | 5 |
| Basic mechanical checks | б |
| Front bolt torque | 7 |
| Print bed clamp system | 8 |
| Remove bed suspension | |



Introduction

This guide aims to help customers who have assembled a BQ Hephestos 2 get the maximum out of their 3D printer and troubleshoot any issues with the auto - levelling feature.

There are some assembly mistakes that can cause the mechanical structure to be deformed, especially in the Y axis. This means the print bed will not move in a perfect plane over its full area, causing the levelling algorithm to fail in some places. This can happen even if the print bed and inductive sensor are in good working order.

There are many factors to consider since each customer assembles the printer in slightly different ways. The tips and tricks contained in this document are the result of extensive testing and have proved to fix one or more levelling issues. However, they might not all be appropriate for a particular printer. Please take this guide as a reference for ideas to try, not as a must-do checklist!

Updating firmware

The first and possibly most effective action is to update the firmware on your Hephestos 2. The latest version fixes some bugs regarding the heated bed and introduces 9-point mesh levelling. This adds a few more seconds to the levelling routine at the beginning of each print, but allows the FW to adjust the Z-height much more accurately, since it does not assume that the print surface is a plane.

Simply updating the FW can fix many levelling issues. To do so, download the BQ firmware updater or the latest version of the firmware from this link: <u>https://www.bq.com/es/support/hephestos-2/support-sheet?ssess=5afe90e1e9ef7&sorigin=productList</u>

First layer settings

The success of the first layer depends greatly on the parameters used. The following table lists the minimum recommended parameters for the first layer:

| Layer height | ≥ 0.2mm | Even if the rest of the print uses a different layer height, make sure the first layer is at least 0.2mm thick. |
|-----------------|--------------|--|
| Extrusion width | ≥ 0.4mm | Increasing the extrusion width on the first layer can improve adhesion to the print bed. Recommended value: 0.48. |
| Layer speed | 15 - 20 mm/s | Printing the first layer slowly dramatically decreases the chances of a failed print. |

Remember these parameters **apply only to the first layer**. The rest of the part can be printed with any other values.



Test Gcode

When making changes to the printer's mechanics, it is important to always print the same pattern. This way, we can evaluate if the change had the desired effect.

You can download BQ's standard test Gcode here.

Before printing the Test Gcode:

- Run the Offset calibration routine so the nozzle height is correct.
- Make sure that Autolevelling is ON in the settings menu
- Leave the manual levelling knobs at the same height (about halfway).
- DO NOT touch the manual knobs when the Gcode is printing! We need to see the result without human intervention in the levelling process.



Test example:





Basic mechanical checks

- 1) Make sure the X-axis is parallel to the print bed. Picture 1a shows an X-axis that is not leveled because the right side is higher than the left. Adjust the height of one side by turning the Z-coupling while holding the other in place (picture 1b).
- 2) Adjust the set screws that hold the Y axis to the printer frame (picture 2a). Do not use excessive torque but make sure they are firmly in place (picture 2b).
- 3) Adjust the rubber foot so the front of the printer is properly supported. Start with the foot above its normal position (picture 3a) and screw it in until you feel the weight that it is holding (picture 3b)





Front bolt torque

The most common mechanical issue is over-tightening the 4 bolts that hold the Y-axis in the front bracket. This warps the Y-axis linear guides and causes the bed to move in a non-planar fashion. To solve this issue, follow these steps:

- 1) Unscrew the 4 bolts in the front bracket until they are loose (not creating any pressure against the bracket)
- 2) Jiggle the bracket in both directions so the linear guides have a chance to settle in a new position.
- 3) Retighten the bolts without any pressure, so you can turn them by hand





Test result:

After loosening the front bolts, the test Gcode shows that the top-left and the bottom-right corners have been fixed and have proper adhesion.

The center square still seems to be too high, so further tweaks are necessary.



Print bed clamp system

If the bed is not sitting flat on the Y-axis, putting pressure on the tabs to hold it in place could cause the bed to warp slightly and cause issues in the center area of the bed.

A solution to this problem is to print <u>this part</u> as an alternative. It holds the bed in place without pressure from the top, using the same holes as the original system.



The bracket holds the side wings of the print bed and fits in the holes of the original system







Notes:

This solution constrains the movement of the bed in the Y axis. If the bracket is not properly printed (or print speed is too high), the bed might move slightly when in use. Make sure the bracket is properly fitted to the bed.

Depending on the material used to print the bracket, it might not be suitable for use with an Hephestos 2 fitted with a heated bed.





Remove bed suspension

In case the manual levelling is not working correctly due to a problem with the springs, it can be easily removed to have autolevelling only. In this case, the bed is supported by the lower sheet metal instead of floating a few millimeters above it. This can help with consistency issues and can easily be reversed if it does not have the desired effect.

