



- 1. Z-Axis Screw
- 2. Platform Fixed Block
- 3. Resin Tank
- 4. Inspection Hatch
- 5. Z-Axis Guide

- 6. UV Cover
- 7. Power Connector and Switch
- 8. Ethernet Port
- 9. USB Port

- 10. Platform
- 11. LCD Screen
- 12. Touchscreen
- 13. Carbon Filter